

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DA516
East
1/2-1
0.807 mi.
4260 ft.

V877 SUBMERSABLE VAULT
NEPTUNE AVE/E 5TH ST
BROOKLYN, NY

NY Spills S103829537
N/A

Site 2 of 3 in cluster DA

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: V877 SUBMERSABLE VAULT
Address: NEPTUNE AVE/E 5TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9815448 / 1999-03-31
Facility ID: 9815448
Facility Type: ER
DER Facility ID: 169598
Site ID: 203954
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-03-29
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1999-03-29
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-03-29
Spill Record Last Update: 2000-06-19
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: STEVE ROMERO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT CON ED E2MIS NOTES An undiaperable sheen found on 200 gals, of water. Sample taken with 4-6 hr. priority. Pressure tested unit, OK. No sewers or waterways affected. Spill is contained. Tag installed #08250 Cleanup pending test results. 3-29-99 18:45 Lab Seq# 99-03187, <1.0ppm PCB 3-30-99 1330 Cleanup complete and tag removed. Incident Closed. "

Remarks: "SHEEN ON WATER IN VAULT-HAS BEEN CONTAINED-PENDING SAMPLE RESULTS CLEANUP WILL TAKE PLACE- CON ED#123930 "

All Materials:

Site ID: 203954
Operable Unit ID: 1076472
Operable Unit: 01
Material ID: 569239
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Units: G
Recovered: .00
Oxygenate: Not reported